CAT 374E

Machine Visibility

Machine Reference Points
y = Machine Centre
x = Machine Centre
z = Machine Counter Weight

Blind spot area
@ 1m high

x

Z

□ =0.5m

SPILLARD
safety systems

©2014 Spillard Safety Systems Limited. All Rights Reserved

CAT 374E

Enhanced Visibility

Machine Reference Points
y = Machine Centre
x = Machine Centre
z = Machine Counter Weight

x

Z

□ =0.5m



SPILLARD
safety systems

©2014 Spillard Safety Systems Limited. All Rights Reserved

CAT 374E

Comparison

Machine Reference Points
y = Machine Centre
x = Machine Centre
z = Machine Counter Weight

Blind spot area
@ 1m high

x

Z

□ =0.5m

SPILLARD
safety systems

©2014 Spillard Safety Systems Limited. All Rights Reserved