



Atlas 1604

Machine Visibility


Machine Reference Points
 y = Machine Centre
 x = Machine Centre
 z = Machine Counter Weight

Distances where blind spot areas intersect machine reference lines

Y

X

Z



□ = 0.5m

- Recommendations
- 1 x SC010 drivers side
 - 1 x NC100 off side
 - 1 x BB052 rear






Atlas 1804

Machine Visibility


Machine Reference Points
 y = Machine Centre
 x = Machine Centre
 z = Machine Counter Weight

Distances where blind spot areas intersect machine reference lines

X



Z



□ = 0.5m

- Recommendations
- 1 x SC010 drivers side
 - 1 x NC100 off side
 - 1 x BB052 rear





Atlas 1604

Machine Visibility


Machine Reference Points
 y = Machine Centre
 x = Machine Centre
 z = Machine Counter Weight

Distances where blind spot areas intersect machine reference lines



X

Z



□ = 0.5m

- Recommendations
- 1 x SC010 drivers side
 - 1 x NC100 off side
 - 1 x BB052 rear

