




CAT 336F

Machine Visibility





CAT 336F

Convex Mirrors

Y

Machine Reference Points
 y = Machine Right
 x = Machine Track Front
 z = Machine Counter Weight

Visibility through standard flat mirrors @ 1m high

X

Visibility through Nc100 convex mirrors @ 1m high

Z



□ = 0.5m



Comparison

