




Volvo L120C

Machine Visibility




No visibility through mirrors, both obscured





Volvo L180D

Machine Visibility - Enhanced



Recommendations

2 x NC100 Convex wing mirrors
 Arms will need extending or adjusting
 to see both flat and convex mirrors
 through obstructions

