




JCB 2CX

# Machine Visibility

□ = 0.5m

Machine Reference Points  
 y = Machine Centre  
 x = Front Wheel Centre  
 w = Rear Wheel Centre

Distances where  
 blind spot areas intersect  
 machine reference lines  
 A= m




The blind spot is not measured at 1m high,  
 it is the blind area from the driving position





JCB 2CX

# Options



## Options

Highlight within the cab that blindspots are present on this newer model of 2CX compared to older model .  
 Advise all operators of blindspots and that they must operate the newer 2CX in a different manor to older models.

And/Or

Replace flat mirrors with NC100 mirrors fitted in position and angle shown.